

## Application Note – Drivers for Digital Audio Interface - Powermate and CMS

Powermate and CMS mixing consoles (generation 3) are equipped with a 4x4 USB 2.0 digital audio interface. Part of delivery is also a license for Cubase LE production software.

Unlike describes in older versions of the user manual the DVD has been replaced by a sheet with a unique licenses number to obtain the latest version via download.

Device drivers previously supplied with the DVD for Windows and MAC operating system can now be found on the Dynacord website under support/downloads.

Due to changes in the various operating system we maintain these drivers and provide updates.

If your OS is a newer version than listed here, we suggest to downgrade to the last supported version.

### WINDOWS

Latest USB driver (2.9.95.2) supports Windows Vista, 7, 8 and 10<sup>\*)</sup>, both 32- and 64-bit versions

One driver supports all Powermate and CMS versions.

<sup>\*)</sup> up to version 1909.

Other Software			
Name	Size	Date	
USB Audio Interface Driver Win10	ZIP	5.89MB	12.06.2019

### Mac OS

Different drivers for CMS/Powermate 600<sup>3</sup> and CMS/Powermate 1000<sup>3</sup>, 1600<sup>3</sup>, 2200<sup>3</sup>.

USB-Audio_1000_Driver_3.3.11_macOS-Sierra_HighSierra_Mojave	ZIP	1.85MB	11.05.2018
USB-Audio_600_Driver_3.3.11_macOS-Sierra_HighSierra_Mojave	ZIP	1.85MB	11.05.2018
USB Audio Interface driver Mac OSX (Intel) V2.0.7 / 1000-3, 1600-3, 2200-3	ZIP	1.07MB	08.09.2012
USB Audio Interface driver Mac OSX (Intel) V2.1.7 / 600-3	ZIP	751KB	08.09.2012
USB Audio Interface driver Mac OSX Mountain Lion V2.2.3 / 1000-3, 1600-3, 2200-3	ZIP	2.35MB	11.20.2012
USB Audio Interface driver Mac OSX Mountain Lion V2.2.3 / 600-3	ZIP	2.35MB	11.20.2012
USB Audio Interface driver Mac OSX Yosemite 3.3.1 / 1000-3, 1600-3, 2200-3	ZIP	1.59MB	02.17.2015
USB Audio Interface driver Mac OSX Yosemite 3.3.1 / 600-3	ZIP	1.59MB	02.17.2015

A driver to support Mac OS BigSur (11.0) is not available.