

N8000 / P64 Firmware Update V1.26.1 Release Notes

This document contains late-breaking product information, updates, and troubleshooting tips for Dynacord P64 and Electro-Voice N8000 Digital Matrix Manager.

What's new

N8000 / P64 Firmware 1.26.1 includes the following bug fixes and enhancements:

- Fixes an issue where the CM-1 module might reset when the devices processor load is high
- Fixes an issue where the processor load of the device increases with open CAN bus connection
 - To disable the CAN-Bus process, open the N8000 / P64 Webserver and navigate to "System Settings" -> "CAN Setup", uncheck the "Enable CAN Handler" checkbox and press the "Save Settings" button

New Firmware Versions:

- N8000_V1.26.1.8521.pkg - to be used with IRIS-Net 4.0.0.