

Technical Note - Drivers for Digital Audio Interface - PowerMate and CMS

PowerMate-3 and CMS-3 mixing consoles are equipped with a 4x4 USB 2.0 digital audio interface. Part of delivery is also a license for Cubase LE production software.

Drivers for Windows and MAC operating system can be found on the Dynacord website : PowerMate - Other Software.

WINDOWS

PowerMate-3 and CMS-3 updated version*

USB Audio Interface Driver 3.0 supports Windows 10 and 11, 64-bit and USB 3.0 (and higher) interface. One driver supports all PowerMate and CMS versions.

* indicated in the upper right corner of the product label on the rear panel as HW:03.



PowerMate-3 and CMS-3 original version

USB Audio Interface Driver Win10 supports Windows Vista, 7, 8, 10 and 11, both 32- and 64-bit versions. One driver supports all PowerMate and CMS versions.

Note on USB > 2.0: PCs with USB 3.0 (and higher) interfaces are in many cases not compatible with the hardware in PowerMate/CMS, which could result in potential audible artifacts.



Mac OS

PowerMate-3 and CMS-3 updated version*

Class compliant with MAC OS and iOS, no driver required.

*indicated on the upper right corner of the product label on the rear panel as HW:03.

PowerMate-3 and CMS-3 original version

Different drivers for CMS/PowerMate 6003 and CMS/PowerMate 10003, 16003, 22003.

USB-Audio_1000_Driver_3.3.11_macOS-Sierra_HighSierra_Mojave	ZIP	1.85MB	11.05.2018
USB-Audio_600_Driver_3.3.11_macOS-Sierra_HighSierra_Mojave	ZIP	1.85MB	11.05.2018
USB Audio Interface driver Mac OSX (Intel) V2.0.7 / 1000-3, 1600-3, 2200-3	ZIP	1.07MB	08.09.2012
USB Audio Interface driver Mac OSX (Intel) V2.1.7 / 600-3	ZIP	751KB	08.09.2012
USB Audio Interface driver Mac OSX Mountain Lion V2.2.3 / 1000-3, 1600-3, 2200-3	ZIP	2.35MB	11.20.2012
USB Audio Interface driver Mac OSX Mountain Lion V2.2.3 / 600-3	ZIP	2.35MB	11.20.2012
USB Audio Interface driver Mac OSX Yosemite 3.3.1 / 1000-3, 1600-3, 2200-3	ZIP	1.59MB	02.17.2015
USB Audio Interface driver Mac OSX Yosemite 3.3.1 / 600-3	ZIP	1.59MB	02.17.2015

Driver not listed are not available.